

Customer	NOKIA
Product name	PBA-200G PARENT BOARD
Product P/N	ALC3H-8DG62165AAAA

Material description	ICFPGA5SGXMA7N2F45I3NStratix5B
Material P/N	ALC3-1AB310260004_REP
Manufacturer NAME and P/N	ALTERA 5SGXMA7N2F45I3N

Date of issue: 1.08.2019

Problem description: SMBIP8 error detected at Obelix Line receiver; Client Far Loopback KO; Gearbox Loopback OK.

Detected by: NOKIA R&D

I. Quantity affected: 1pc.

II. Where used information:

TIMI REPAIR ID	Trieste REPAIR ID	ITEM SERIAL NUMBER
F2019-0068	N/A	EZ1536B4724

III. Component information

ITEM SERIAL NUMBER	MATERIAL SERIAL NUMBER OR LOT NO.	MATERIAL DATE CODE&PART MARK
EZ1536B4724	NFEAR33833 406FA3X0C	1531

IV. Containment plan

- 1) **Inspection mode: visual inspection passed**
- 2) **Acceptable criteria: conform data sheet**
- 3) **Re-action: Reject affected component**
- 4) **Observation:**

1. **Inform component supplier about this problem;**
2. **Supplier should investigate the cause of the failure.**