

Customer	NOKIA
Product name	PBA 100G SD FEC LINE DAUGHTER
Product P/N	ALC3H-8DG60959AAAE

Material description	ICFPGAEP4S100G5H40I1NStratix4BGA/1517654-I/O531000-40C/100C OBELIX 100
Material P/N	ALC3-1AB227640008_REP
Supplier NAME and MPN	ALTERA EP4S100G5H40I1N

Date of issue: 1.08.2019

Problem description: SFI issue ADD2 to Obelix at room temperature 25°C

Detected by: R&D Nokia

I. Quantity affected: 1pc.

II. Where used information:

TIMI REPAIR ID	Trieste REPAIR ID	ITEM SERIAL NUMBER
F2019-0081	N/A	EZ1603B4391

III. Component information

ITEM SERIAL NUMBER	MATERIAL SERIAL NUMBER OR LOT NO.	MATERIAL DATE CODE&PART MARK
EZ1603B4391	NDFAG62811 481HA5X0J	1549

IV. Containment plan

- 1) **Inspection mode: visual inspection passed**
- 2) **Acceptable criteria: conform data sheet**
- 3) **Re-action: Reject affected component**
- 4) **Observation:**

**1. Inform component supplier about this problem;
2. Supplier should investigate the cause of the failure.**